


LAND CORNER RECORD

1. T. 5 S R. 35 E No. E23 Cor. 1/4 Mer. Will State Oregon N. F. Wallace Whitman Dist. LaGrande

2. Corner Status

E-23



7. Photo Identification

Photo No. DVD-57 9M-45

Ident. By: J. Hoyt

8. Plane Coordinate Position Data

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Field Book No. \_\_\_\_\_

Where Filed \_\_\_\_\_

9. Evaluation

Authentic \_\_\_\_\_

Needs Verif. \_\_\_\_\_ Monument DD

Re-estab. \_\_\_\_\_ Survey \_\_\_\_\_

Land Status \_\_\_\_\_

3. Original Description \_\_\_\_\_ Vol. \_\_\_\_\_ Page \_\_\_\_\_ Where Recorded \_\_\_\_\_

4. Description of Corners: Established 1882 by G.L.D. contract survey.  
Set a post 3' long, 3" sq., 24" in ground for 1/4 cor. marked 1/4 S  
on N. face, from which a 7" pine bears S47°E, 42 lxs. A 7" pine  
bears N43°W 27 lxs. Both marked 1/4 S B.T.

5. Investigation Notes: Found metal postter (W.P.G. 1938) and  
rotten post nearby.

6. Signed J. Hoyt Title Survey Tech Date 4-2-67

UNION COUNTY SURVEYOR

Date Received \_\_\_\_\_

Date Filed 12-23-87

By G. LANGLITZ, DEPUTY

File No. 346-87R

E-23