45

History of original corner establishments

Original survey by General Land Office Contract Survey
The original notes read;
Run north on west side of Sec 18 and set a post from which;
A pine 32" in diam bears N83°W 52 lks dist marked †SBT
A pine 14" in diam bears S27°E 57 lks dist marked ‡SBT

	-25
DIAGRAM	
T5	
R34E	R35EWM
\$13	<b>8</b> 18

Found - A pine stump bears \$27°E

A pine stump and log bears N83°W




Description of monument and accessories I established to perpetuate the

At the position of the corner I set a 2 galvanized pipe 30 long with a bronze cap on top and 8 plated welded to bottom Pipe set to a depth of 18 and backfilled with some and soil and raised a stone monument;

I stamped the disk

From the corner the original bearing trees are - none; I set the following new bearing trees; A pine 10" in diam bears N29°E 8.5 ft. marked \$SBT A pine 10" in diam bears N55°W 24.2 ft. marked \$SBT (distance to center of trees and marked with scribe)



I set a steel fence post with USFS sign54-4 attached. USFS bearing tree signs were placed on the bearing trees shoulder high facing the monument.

Office of County Surveyor  State of Oregon , I hereby con	County of	PILMS INS.	UNTY
for record on the .10 day of .Sapt		m, (signed)	
(COUNTY OFFICIAL)	by	Date Received	
		Date Filed	
		Ву	
		File No. 583-	84 R

Form BR. 71 M. 57 10 /201