


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. N-03

History of original corner establishment:

In 1882, under Contract No. 481, Rufus S. Moore set a post, from which a 12" Pine bears S50°E, 36 lks. and a 10" Pine bears N62°W, 30 lks.



Description of corner evidence found:

No corner monument or other evidence found.

Description of monument and accessories established to perpetuate the original location of this corner: Cap is stamped:

Corner set by single proportionate measurement.

T5S R35E

1/4 $\frac{S}{S}$ $\frac{18}{19}$

RLS 1844
1984

Set 2.5" aluminum cap on 2"x30" aluminum pipe rising 13" above ground in rock and earth mound. Set steel fence post 4.0 ft. west of corner.

New BT's:

- A 6" L. Pine bears N65°W, 38.6 ft., blazed and scribed: 1/4 S18 BT.
- A 9" L. Pine bears S9°E, 59.0 ft., blazed and scribed: 1/4 S19 BT.

Attached brass disk stamped LS 1844 to base of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Corner is found 2.0 ft. north of east-west fence. Take road 5155-500 to road 5155-510, south to fence, 1200 feet west along fence to corner.

Compass Declination: 19 1/2°E

Witness: Jeff Sheets

I hereby certify the above described corner monument and/or accessories was established as described on November 6, 1984.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David E. Scott

OREGON
JULY 13, 1929
DAVID E. SCOTT
1844

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 1-23-85

Date Filed 2-5-85
REG-798-276

By G. LANGUITZ, DEPUTY

File No. 1-85R