## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1882, under Contract No. 481, Rufus S. Moore set a post, from which an 18" Pine bears N43°E, 197 lks. and pits were dug north and south of the post at a distance of 5.5 ft.

Index File No.	P-0
DIAGRAM	
T5S R35E 1/4 19 20	
19720	

## Description of corner evidence found:

No corner monument found.

Bearing trees found:
A 24" L. Pine bears N43°E, 130.0 ft., with blazed face, badly rotted with no scribing. On it was a location poster dated 1946 and marked: Fd BT.

Description of monument and accessories lestablished to perpetuate the Cap is stamped: T5S R35E original location of this corner: Set 2.5" aluminum cap on 2"x30" aluminum pipe 1/4 rising 6" above ground. Set steel fence post S19+S20 3.0 ft. north of corner. **RLS 1844** 

New BT's:

A 16" L. Pine bears N48°04'E, 262.5 ft.,

scribed: 1/4 S20 BT.

A 9" L. Pine bears S26°53'W, 642.9 ft., scribed: 1/4 S19 BT.

Attached brass disk stamped LS 1844 to base of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Corner is found 125 ft. south of fence in swampy area. Location posters on fence posts. 1000 ft. west of road 5155.

Compass Declination: 19 1/2°E Witness: Jeff Sheets

I hereby certify the above described corner monument and/or accessories was established as described on November 7, 1984.

REGISTERED PROFESSIONAL AND SURVEYOR OREGON DAVID E. SCOTT

File No 5-85 R

1984

Office of	•	
for record on the day ofby	, 19	Uthon County Surveyor
(COUNTY OFFICIAL)	(DEPUTY)	
Form R6-7100-57 (9/71)		Pote Received 1-33-85 ★ apo - 798-276  Date Filed 2-5-85
		By G. LANGLITZ DEPUTY