CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This is not an original G.L.O. corner.

Index File No. P-06

DIAGRAM

T5S R35E

CW 1/16
S 20

Description of corner evidence found:

No corner evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is stamped:

T5S R35E

Corner set by subdivision of section.

Set 2.5" aluminum cap on 2"x30" aluminum pipe rising 6" above ground. Set steel fence post 3.0 ft. east of corner.

CW 1/16 S 20 RLS 1844 1984

New BT's:

A 6" L. Pine bears S 17°E, 19.9 ft., blazed and scribed: CW 1/16 S20 BT. An 8" L. Pine bears N86.5°E, 20.6 ft., blazed and scribed: CW 1/16 S20 BT.

Attached brass disk stamped LS 1844 to base of blazes. Painted blazes and attached signs as per <u>Standard Specifications for Cadastral Surveys</u>, USFS Region 6, March 1982.

Corner is found on north slope 40 ft. below ridge top. Take road 5155 0.4 mi. past Blue Springs. Walk east up ridge to posted line.

Compass Declination: 19 1/2°E Witness: Jeff Sheets

I hereby certify the above described corner monument and/or accessories was established as described on November 7, 1984.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 13, 1979
DAVID E. SCOTT
1844

BY G. LANGENTZ DEPUTY

Office of Cour	nty of	
State of		UNION COUNTY SURVEYOR
(COUNTY OFFICIAL)	(DEPUTY)	
Form R6-7100-57 (9/71)		# GPO-798.276 to Fied 2-5-85