


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This is not an original G.L.O. corner.

Index File No. P-08



Description of corner evidence found:

No corner evidence found.

Description of monument and accessories | established to perpetuate the original location of this corner:

Cap is stamped:

Corner set by subdivision of section.

T5S R35E

Set 2.5" aluminum cap on 2"x30" aluminum pipe rising 6" above ground. Set steel fence post 3.0 ft. north of corner.

C  $\frac{E \ 1/16}{S \ 20}$  C

RLS 1844  
1984

New BT's:

A 5" Fir bears S63°E, 22.0 ft., blazed and scribed: CE 1/16 S20 BT.

A 7" Tamarack bears N31.5°E, 47.1 ft., blazed and scribed:

CE 1/16 S20 BT.


Attached brass disk stamped LS 1844 to base of blazes. Painted Blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Corner is found 90 ft. west of a 24" fir with location poster which is 25 ft. west of road 5155-085, 0.3 mile from road 5155-084.

Compass Declination: 19 1/2°E

Witness: Jeff Sheets

I hereby certify the above described corner monument and/or accessories was established as described on November 6, 1984.



Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

**WAGON COUNTY SURVEYOR**

---

Received 1-23-85

★ GPO-798-276  
Filed 2-5-85

By G. LANGRISH, DEPUTY

File No. 8-85 R