


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. Q-05

History of original corner establishment:

Not an original G.L.O. corner.



Description of corner evidence found:

No corner evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

Corner set by single proportioning.

Set 2.5" aluminum cap on 2"x30" aluminum pipe rising 5" above ground. Set steel fence post 3.0 ft. east of corner.

Cap is stamped:

T5S R35E
S1/16
S19 S20
RLS 1844
1984

New BT's:

7" L. Pine bears S32°W, 29.6 ft., blazed and scribed: S1/16 S19 BT.

7" L. Pine bears N75 1/2°E, 66.5 ft., blazed and scribed: S1/16 S20 BT.


Attached brass disk stamped LS 1844 to base of each blaze. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Corner is found at corner of timber. Area north and west has been clear cut. From the SW 1/16 along road 5155, walk west to corner.

Compass Declination: 19 1/2°E

Witness: Jeff Sheets

I hereby certify the above described corner monument and/or accessories was established as described on November 9, 1984.



Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

| | |
|-----------------------|---------------------|
| UNION COUNTY SURVEYOR | |
| Received | 1-23-85 |
| ☆ GPO-799-276 | |
| Filed | 2-5-85 |
| By | G. LANGLITZ, DEPUTY |
| File No. | 9-85 R |