CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This is not an original G.L.O. corner.

Index File No. Q-06

DIAGRAM

T5S R35E

SW 1/16.S20

Description of corner evidence found:

No corner evidence found.

Description of monument and accessories | established to perpetuate the original location of this corner:

Corner set by subdivision of section.

T5S R35E

Set 2.5" aluminum cap on 2"x30" aluminum pipe rising 8" above ground. Set steel fence post 3.0 ft. north of corner.

SW 1/16 \$20

RLS 1844 1984

New BT's:

A 6" L. Pine bears N8°E, 59.3 ft., blazed and scribed: SW 1/16 S20 BT. A 6" L. Pine bears N89°E, 57.3 ft., blazed and scribed: SW 1/16 S20 BT.

Attached brass disk stamped LS 1844 to base of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Corner is found in a swamp 75 ft. south of road 5155, 1000 ft. west of cabins at Blue Spring.

Compass Declination: 19 1/2°E Witness: Jeff Sheets

I hereby certify the above described corner monument and/or accessories was established as described on November 7, 1984.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
OREGON
JULY 13, 1979
DAVID E. SCOTT
1844

Office of	Number of			
State of	only or			
The state of the s	the wish in the	this office		
	···· <i>, 19.</i>	-	4.000	COUNTY
(COUNTY OFFICIAL)			7.2	'EYOR
	(DEPUTY)	•••••••••••••••••••••••••••••••••••••••	7	
-7100-57 (0/71)			•	

Form R6-7100-57 (9/71)

#GPO-798.276 2-5-85

Fre No. 10 - 85 P