


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. Q-23

History of original corner establishment:

This is not an original GLO corner.



Description of corner evidence found:

No corner monument or other evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

Cap is stamped:

Corner set by subdivision of section.
Set 2.5"x30" aluminum capped aluminum pipe rising 6" above ground. Set steel fence post 3.0 ft. west of corner.

T5S R35E
C
S1/16 | S24
C
RLS 1844
1985

New BT's:

- 6" P. Pine bears S74 3/4°W, 89.8 ft., blazed and scribed: CS 1/16 S24 BT.
- 14" P. Pine bears S23°W, 160.4 ft., blazed and scribed: CS 1/16 S24 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

To find corner, take road 51 north 1/4 mile from road 5125. Corner is on bare hillside, visible from road.

Compass Declination: 19 1/2°E

Witness: Bernie Sutton

I hereby certify the above described corner monument and/or accessories was established as described on May 5, 1985.



Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by (COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR

Date Received 9-18-85

Date Filed 9-23-85

By G. LANGLITZ DEPUTY

File No. 61-85 R