CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1882, under Contract No. 451, Rufus S. Moore set a post, from which a 6 mPine bears S32°E, 14 lks. and a 6" Pine bears N25°E, 36 lks.

Index File No. R-19

DIAGRAM

T5S R35E

1/4 S23

\$\frac{\$523}{\$526}

Description of corner evidence found:

No corner monument or evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is stamped:

Corner set by single proportioning.
Set 2.5"x30" aluminum capped aluminum pipe
rising 6" above ground. Set steel fence
post 3.0 ft. north of corner.

T5S R35E 1/4<mark>S 23</mark> 1/4<mark>S 26</mark> RLS 1844 1985

New BT's:

- 8.5" Fir bears N8.5°E, 54.5 ft., blazed and scribed: 1/4 S23 BT.
- 6.5" W. Larch bears S53°E, 24.9 ft., blazed and scribed: 1/4 S26 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

Corner is on east slope above ravine. Road 5100-257 is in bottom of ravine. Take Road 5100-295 to Road 5100-290 to CN1/16 S26, then go north 1/4 mile to corner.

Compass Declination: 19 1/2°E Witness: Herb Hamerlynck

I hereby certify the above described corner monument and/or accessories was established as described on May 3, 1985

OREGON JULY 13, 1979 B. A. SUTTON 1 8 4 8

PROFESSIONAL

SURVEYOR

Office of	County of	
State of , I hereby certify that for record on the day of	the within instrument was filed in this diffice UNION COUNTY	-
(COUNTY OFFICIAL)	(DEPUTY)	-
Form R6-7100-57 (9/71)	Date Received 9 - 18 - 85 \$\times \text{pro} - 798.276 Date Filed 9 - 23 - 85	