CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The original rangevline between, R34E and R35E was by L1. Coopers under Contract No. 397, approved April15,11882. Set a post, from which a 26" Pine bears N65°W, 198 lks. and an 8" Pine bears S20°E, 56 lks.

Index File No. T	1
DIAGRAM	7
T5S R34E R35E 1/4 25 \ 30	

T5S

1/4

R34E R35E

RLS 1844

1984

Description of corner evidence found:

No corner monument found. Small pile of rocks at corner location. Notes call for "post".

One bearing tree found: A 34" P. Pine bears N65°W, 130.7 ft. headed face.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 7" above ground. Cap is stamped:

Steel fence post 3.0 ft. north of corner.

New BT: A 6" Fir bears N87°E, 86.5 ft., blazed and scribed: 1/4 S30 BT.

Brass LS 1844 disc in lower end of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E Witness: Duane Scott

Corner is found on east side of strip cleared for fine line. 200 ft. south clearing, 1800 ft. south Lookout Cr. 750 ft. east of Rd 5166-065 28 ft. west of fence.

I hereby certify the above described corner monument and/or accessories was established as described in June of 1984.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON

JULY 13. 1979

DAVID E. SCOTT

1844

Office of	County of	•
otate of the certify	that the within instrument was filed	in this office UNION COUNTY
	······· , 13	
(COUNTY OFFICIAL)	(DEPUTY)	

Form R6-7100-57 (9/71)

Date Filed GPO 798-24-84

By G. LANGLITZ DEPUTY

File No. 968-84 R