CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1882, under Contract No. 381, Rufus S. Moore set a post, from which a 4" Pine bears N42°E, 86 lks. and a 7" Pine bears S53°W, 48 lks.

Index File No. T-05

30 29

DIAGRAM
T5S R35E
1/4

Description of corner evidence found:

No corner monument found.

Bearing trees found:

An 18" Pine bears S53°W, 31.6 ft., dead and down, scribed: 1/4 S BT.

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is stamped:

Set a 2.5" aluminum cap on 2"x30" aluminum pipe rising 6" above ground. Set steel fence post 3.0 ft. north of corner.

T5S R35E 1/4 S30 S29 RLS 1844

1984

New BT's:

A 9" Tamarack bears S63.5°E, 213.0 ft.,

scribed: 1/4 S29 BT.

An 8" Fir bears N74°W, 59.9 ft., scribed: 1/4 S30 BT.

Attached brass disk stamped LS 1844 to base of blazes. Painted blazes and attached signs as per <u>Standard Specifications</u> for <u>Cadastral Surveys</u>, USFS Region 6, March 1982.

Corner is found on west side of swampy meadow N37°E, 500 ft. from dam forming pond. Main east-west road through Vey Ranch is 2000 ft. south of corner.

Compass Declination: 19 1/2°E Witness: Jeff Sheets

I hereby certify the above described corner monument and/or accessories was established as described on November 7, 1984.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 13, 1979
DAVID E. SCOTT
1844

Office of	County oft the within instrument was filed in	this Toffice
ror record on the day of, 19		UNION COUNTY
(COUNTY OFFICIAL)	(DEPUTY)	SURVEYOR
Form R6-7100-57 (9/71)		Data Received 1-23-85
, , , , , , , , , , , , , , , , , , ,		# GPO—798-276 Data Filed 2-85-85