

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This is not an original GLO corner.

Index File No. T-11

DIAGRAM
T5S R35E
C1/4•S.28

Description of corner evidence found:

No corner monument or evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is stamped:

Corner set by intersection.
Set 2.5"x30" aluminum capped aluminum pipe rising 6" above ground. Set steel fence post 3.0 ft. north of corner.

T5S R35E
C1/4•S28
RLS 1844
1985

New BT's:

7" D. Fir bears S77.25°E, 60.6 ft.,
blazed and scribed: C1/4 S28 BT.
6.5" W. Larch bears S12.5°W, 62.3 ft.,
blazed and scribed: C1/4 S28 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

Corner is in timber on north slope 600' south of Road 5155-043, 1500' east of Road 5155-073. Take Road 5155-070 to 5155-073 0.3 miles to beginning of clear cut, then east to corner.

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>David E. Scott</i>
OREGON JULY 13, 1973 DAVID E. SCOTT 1844

Compass Declination: 19 1/2°E
Witness: Bernie Sutton

I hereby certify the above described corner monument and/or accessories was established as described on April 17, 1985.

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR
Date Received <u>9-18-85</u>
Date Filed ^{☆GPO 7-00-23} <u>9-23-85</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>69-85 R</u>