


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. T-19

History of original corner establishment:  
This is not an original GLO corner.



Description of corner evidence found:  
No corner monument or other evidence found.

Description of monument and accessories | established to perpetuate the original location of this corner:

Cap is stamped:

Corner set by intersection.  
Set 2.5"x30" aluminum capped aluminum pipe rising 12" above ground. Set steel fence post 3 ft. north of corner.

T5S R35E  
C1/4•S26  
RLS 1844  
1985

New BT's:  
5" Black Pine bears S46°E, 29.1 ft., blazed and scribed: C 1/4 S26 BT.  
3" P. Pine bears N4°W, 27.4 ft., blazed & scribed: C 1/4 S26 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

Corner is in a clearing 24 ft. south of east-west fence on top of ridge that runs north to south. Take Road 51 to Road 5100-295 north to fence 0.25 mi. east along fence to corner.

Compass Declination: 19 1/2°E  
Witness:Bernie Sutton

I hereby certify the above described corner monument and/or accessories was established as described on May 4, 1985.



Office of..... County of.....  
State of..... I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....  
..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR  
Date Received 9-18-85  
Date Filed 9-23-85  
By G. LANGLITZ, DEPUTY  
File No. 73-85 R