


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. U-09

History of original corner establishment:

This is not an original G.L.O. corner.



Description of corner evidence found:

No corner monument or other evidence found.

Description of monument and accessories | established to perpetuate the original location of this corner:

Cap is stamped:

Corner set by single proportionment.

T5S R35E
S 1/16
S29 | S28
RLS 1844
1984

Set 2.5" aluminum cap on 2"x30" aluminum pipe rising 24" above the ground in mound of rock and earth. Set steel fence post 5.0 ft. north of corner.

New BT's:

A 6" Fir bears East, 27.4 ft., blazed and scribed: S 1/16 S28 BT.

A 7" Fir bears N12°W, 15.2 ft., blazed and scribed: S 1/16 S29 BT.


Attached brass disk stamped LS 1844 to base of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Corner is found N78°E, 12.0 ft. from fence corner and 470 ft. south of road 5155-072.

Compass Declination: 19 1/2°E

Witness: Jeff Sheets

I hereby certify the above described corner monument and/or accessories was established as described on November 8, 1984.



Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Date Received 1-23-85
☆ GPO-798-276

Date Filed 2-5-85

By G. LANGLITZ, DEPUTY

File No. 19-85 R