


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not an original GLO corner.

Index File No. U-11




Description of corner evidence found:

No corner monument or other evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

Set corner by
2.5"x30" aluminum capped aluminum pipe
rising 8" above ground. Set steel fence
post 3 ft. east of corner.



New BT's:

- 4" Fir bears N65°W, 17.0 ft., blazed and scribed: "x" BT.
- 6" Fir bears N23°E, 10.8 ft., blazed and scribed: CS 1/16 S28 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "1844" nailed to lower end of blazes.

Corner is 36.5 ft. north of fence in heavy brush. Take Road 5155.073 to end, go 300 ft. south to fence, then east 3000 ft. to corner.

Compass declination: 19 1/2°

Witness:

I hereby certify the above described corner monument and/or accessories was established as described on April 15, 1985.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David E. Scott

OREGON
JULY 13, 1979
DAVID E. SCOTT
1844

Office of..... County of.....

State of..... I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 9-18-85

Date Filed 9-23-85
GPO-798-276

By G. LANGLITZ, DEPUTY

File No. 75-85 R