


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This is not an original GLO corner.

Index File No. U-13



Description of corner evidence found:

No corner monument or other evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is stamped:

Corner set by single proportioning.
Set 2.5"x30" aluminum capped aluminum pipe rising 6" above ground. Set steel fence post 3.0 ft. west of corner.

T5S R35E	
S1/16	
S28	S27
RLS 1844	
1985	

New BT's:

- 10" P. Pine bears S66.5°W, 23.6 ft.,
blazed and scribed: S1/16 S28 BT.
- 9" Fir bears S66.5°E, 38.0 ft.,
blazed and scribed: S1/16 S27 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

Corner is 67 ft. north of east-west fence on top of ridge. Take Road 5155 to Road 5155-040 to Road 5155-043 to Road 5155-044. Go to the end of Road 5155-044, then south to fence. Corner is west 1200 ft.

Compass Declination: 19 1/2°E
Witness: Bernie Sutton

I hereby certify the above described corner monument and/or accessories was established as described on April 14, 1985.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 13, 1979
B. A. SUTTON
1848

Office of..... County of.....
 State of..... I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....

..... by

(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 9-18-85

☆ GPO-798-278

Date Filed 9-23-85

By G. LANGWITZ, DEPUTY

File No. 76-85R