


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This is not an original GLO corner.

Index File No. U-15



Description of corner evidence found:


No corner monument or other evidence found.

Description of monument and accessories established to perpetuate the original location of this corner:

Cap is stapped:

Corner set by subdivision.

Set 2.5"x30" aluminum capped aluminum pipe rising 24" above rock in mound of rock. Set steel fence post 8.0 ft. west of corner.



New BT's:

- 7" W. Larch bears N37°W, 45.3 ft., blazed and scribed CS1/16 S27 BT.
- 5.5" D. Fir bears N43.5°E, 14.7 ft., blazed and scribed CS1/16 S27 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

Corner falls in notch in large rock on west side of canyon. Take Road 5155-040 one mile from Road 5155, then walk south to fence. Corner is on a rock at top of west side of canyon.

Compass Declination: 19 1/2°E
Witness: Bernie Sutton

I hereby certify the above described corner monument and/or accessories was established as deccribed on April 14, 1985.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

B. A. Sutton

OREGON
JULY 13, 1979
B. A. SUTTON
1848

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 9-18-85
 Date Filed 9-23-85
 By G. LANGLITZ, DEPUTY
 File No. 77-85 R