CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This is not an original GLO corner.

Index File No. U-18 DIAGRAM T5S R35E SW1/16 **S26**

Description of corner evidence found:

No corner monument or other evidence found.

Description of monument and accessories I established to perpetuate the Cap is stamped: original location of this corner:

Set corner by subdivision. Set a 2.5"x30" aluminum capped aluminum pipe rising 6" above ground.
3.0 ft. west of corner. Set steel fence post

T5S R35E

SW1/16 • S26

RLS 1844

_1985

New BT's:

3" Tamarack bears S18.75°E, 64.6 ft.,

blazed and scribed; X BT. 6" Black Pine bears N46.5°W, 49.1 ft., blazed and scribed: SW1/16 S26 BT.

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

Corner is located in cleared area 18 ft. south of east-west fence, 50 ft. west of fence corner. Take Road 51 to Raad 5155, then 0.2 miles to cattle guard and forest boundary. Corner is 300 ft. south.

Compass Declination: 19 1/2°E Witness: Bernie Sutton

I hereby certify the above described corner monument and/or accessories was established as described on May 5, 1985.

REGISTERED PROFESSIONAL SURVEYOR OREGON JULY 13, 1979 B. A. SUTTON 1 8 4 8

BY G. LANGLITZ DEPUTY

File No. 79 - 85

Office of C	ounty of
for record on the day of	
(COUNTY OFFICIAL)	(DEPUTY) Date Received 9-18-85
Form R6-7100-57 (9/71)	Date Filed 6 9 2 2 3 8 5