


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1882, under GLO Contract 451, Rufus S. Moore set a post from which, at 5.5 ft. east and west, he dug 18x18x12 pits.

Index File No. V-19



Description of corner evidence found:

No corner monument or other evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is stamped:

Corner set by single proportioning.
Set a 2.5"x30" aluminum capped aluminum pipe rising 7" above ground. Set steel fence post 3.0 ft. north of corner.

T5S R35E
1/4 $\frac{S 26}{S 35}$
RLS 1844
1985

Reference Monuments: 36"x5/8" iron rods with 1.5" aluminum caps.

N45°W, 30.0 ft., S45°E, 30.0 ft.,
Cap is stamped: Cap is stamped:

RM	RM
S 26	S 35
RLS 1844	RLS 1844
1985	1985

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Brass disk stamped "LS 1844" nailed to lower end of blazes.

Corner is on flat 400 ft. east of Sheep Creek. Take the north driveway to the building at Vey Ranch. Corner is due east.

Compass Declination: 19 1/2°E
Witness: Bernie Sutton

I hereby certify the above described corner monument and/or accessories was established as described on May 7, 1985.

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

(DEPUTY)

REGISTERED
PROFESSIONAL
LAND SURVEYOR

B. Sutton
OREGON
JULY 13, 1979
B. A. SUTTON
1848

**UNION COUNTY
SURVEYOR**

Date Received 9-18-85

☆ GPO-798-276
Date Filed 9-23-85

By G. LANGLITZ DEPUTY

File No. 83-85 P