CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by General Land Office contract survey
The original notes state;
North between sections 35 and 36.
80.00 Set a basalt stone 16 x 8 x 7%, 11% in ground for corner sections 25, 26, 35, and 36 from which a;
Pine 4% dia bears N34°E, 28 lks marked T5S R35E S25BT;
Pine 40% dia bears N21°W, 122 lks marked T5S R35E S26BT;
Pine 5% dia bears S50°W, 55 lks marked T5S R35E S35BT;
Pine 8% dia bears S7°E, 95 lks marked T5S R35E S36BT;

	V-21
DIAGRAM	
T 58	R35EWM
S 26	S 25
s 35	s 36
,	

COR

S 25

ORE LIC 381

1970

s 26

S 35

R35E

File No. 626-84 R

Description of corner evidence found:

In section 26, found stump with BT.

At the corner, found straps set along side, the monument.

Found slab with scribing in section 26

Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 30 galvanized pipe with an eight inch plate welded to bottom and a bronze cap on top. The hole was back filled with stone and tamped soil.

I stamped the disk.

From the monument the original bearing trees were; (none). I established the following neww bearing trees; Lodge Pole 14° dia Nóó°W at a distance of 18.5 ft. and scribed T5S R35E S26 BT Lodge Pole 12° dia Nó7°E at a distance of 24.8 ft. and scribed T5S R35E S25 BT

Ponderosa Pine 27th dia 368 W at a distance of 61 ft. and soribed T53 R35E 335 BT

Lodge Pole 10" dia 327°E at a distance of 27 ft. and scribed T5S R35E S36 BT. The distance measured to center of respective trees on level. I placed bearing tree signs on both old and new bearing trees and painted stripe around trees. I placed a steel fence post with USFS sign 54-4 attached near the corner and indicated that all four sections were private land.

State of Oregon , I hereby c	certify that the within instrument was filed	in this office CHRYEALD
County Surveyor	by Jan GOEPUTY)	Date Received
		Date Filed

Form R6-7100-57 (9/66)

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1882, under GLO Contract No. 451, Rufus S. Moore set a stone 16x8x7 from which a 4" Pine bears N34°E, 28 1ks., a 40" Pine bears N21°W, 122 1ks., a 5" Pine bears S50°W, 55 1ks., and a 6" Pine bears S7°E, 95 1ks.

Index File No. V-21

| DIAGRAM | T5S R35E | S26 | S25 | S35 | S36 | S36

Description of corner evidence found:

Cap is stamped:

COR T5S R35E

Found a 3" brass cap on a 2.5" iron pipe rising 10" above ground.

T5S R35 S26 S25 S35 S36

Found a 45" Stump bears N21°W, 80.5 ft., marked "BT":

S35 | S36 ORE LIC 381 1970

Found a 30" P. Pine bears S68°W, 61.0 ft., marked "T5S R35E S35 BT".

Description of monument and accessories I established to perpetuate the original location of this corner:

New BT's:

8" P. Pine bears N63°W, 86.5 ft., blazed & scribed: T5S R35E S26 BT. 20" P. Pine bears N3°E, 31.2 ft., blazed & scribed: T5S R35E S25 BT. 18.5" P. Pine bears S63.5°E, 41.0 ft., blazed & scribed: T5S R35E S36 BT.

Attached brass disk stamped LS 1844 to base of blazes. Painted blazes and attached signs as per <u>Standard Specifications</u> for <u>Cadastral Surveys</u>, USFS Region 6, March 1982.

Corner is found on edge of timber on east slope above Sheep Creek. Section Line crosses road 51 at driveway to Vey Ranch. Walk 3/4 mile east.

Compass Declination:19 1/2°E Witness: Bernie Sutton

I hereby certify the above described corner monument and/or accessories was established as described on May 7, 1985.

REGISTERED
PROFESSIONAL
LAVO SURVEYOR

OREGON
JULY 13, 1979
B. A. SUTTON
1 8 4 8

Office of	·····
, 19	iled in this office UNION COUNTY SURVEYOR
(COUNTY OFFICIAL) (DEPUTY)	
Form R6-7100-57 (9/71)	Date Received 9-18-85