CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Index File No. Y-14

DIAGRAM

T5S R35E

SW1/16•S34

RLS 1848

1986

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap is stamped:

Set 2½"x30" aluminum capped aluminum pipe rising 7". No stones available. Set steel fence post 3' east of corner

T5S R35E SW1/16•S34 RLS 1848 1986

New BT's:

a 3" L. Pine bears S55°W, 28.3 ft.,

blazed & scribed: X BT.

an 11" L. Pine bears S38½°E, 105.2 ft., blazed & scribed: W1/16 S34 BT Painted blazes and attached signs as required in <u>Specifications for Cadastral Surveys</u>, USFS Region 6, March, 1982. Attached ¾" brass washers marked RLS 1848 to blazes.

Compass Declination: 19½°E
Witness: J. Sutton
I hereby certify that the above described corner monument and/or accessories was perpetuated as hereon described on Aug 15, 1986.

REGISTERED
PROFESSIONAL
LAND, SURVEYOR

OREGON
JULY 13, 1979

OREGON
JULY 13, 1979
B. A. SUTTON
1 8 4 8

UNION COUNTY
SURVEYOR

Date Received 8-26-86

n to Filed 9-10-86

BY G. LANGUTZ DEPUTY

5 N. 133-86 R

		CONTROL OF THE PARTY OF THE PAR
Office of	County of	See Supre 77-96
State of, I hereby certify	that the within instrument was filed in this	office
for record on the day of	, 19	
	bv	
(COUNTY OFFICIAL)	(DEPUTY)	•••••