CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: None

DIAGRAM T5S R35E S1/16| C

> RLS 1848 1986

Index File No. Y-15

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the Cap is stamped: original location of this corner:

Set 2½"x30" aluminum capped aluminum pipe rising 6". No stones available. Set steel fence north of corner post 3'

T5S R35E S34 /16| RLS 1848

New BT's:

a 7½" Doug. Fir bears N61°W, 78.3 ft., blazed & scribed: CS1/16 S34 BT. a 3" W. Larch bears S43½°W, 25.3 ft., blazed & scribed:

X BT Painted blazes and attached signs as required in Specifications for Cadastral Surveys, USFS Region 6, March, 1982. Attached 3 brass

1986

Compass Declination: 19岁°E Witness: J. Sutton I hereby certify that the above described corner monument and/or accessories was perpetuated as hereon described on May 13, 1986.

washers marked RLS 1848 to blazes.

REGISTERED PROFESSIONAL LAND SURVEYOR **OREGON** JULY 13, 1979 B. A. SUTTON 1 8 4 8

UNION	COUNTY	
SURVEYOR		

Date Received 8.26-86

Office of		
Office of	County of	See S and
Office of		DEF 20KNEY
for record on the day of		27-86
	by	
(COUNTY OFFICIAL)		