


Y-17

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. Y-17

History of original corner establishment:  
None



Description of corner evidence found:  
None

Description of monument and accessories established to perpetuate the original location of this corner:


Cap is stamped:

Set 2½"x30" aluminum capped aluminum pipe rising 6". No stones available.  
Set steel fencepost 3' south of corner.

T5S R35E  
S1/16  
S34|S35  
RLS 1848  
1986

New RP's:

- A 5/8"x36" iron rod with a 1½" aluminum cap bears N89°27'34"W, 30 ft.
- A 5/8"x36" iron rod with a 1½" aluminum cap bears S00°41'05"E, 30 ft.



Painted blazes and attached signs as required in Specifications for Cadastral Surveys, USFS Region 6, March, 1982.

Compass Declination: 19½°E  
Witness: J. Sutton  
I hereby certify that the above described corner monument and/or accessories was perpetuated as hereon described on Aug 5, 1986.



**UNION COUNTY SURVEYOR**

Date Received 8-26-86

Date Filed 9-10-86

By G. LANGLITZ DEPUTY

File No. 135-86 R

SEE SURVEY 27-86

Office of..... County of.....  
 State of....., I hereby certify that the within instrument was filed in this office  
 for record on the..... day of....., 19.....  
 ..... by .....  
 (COUNTY OFFICIAL) (DEPUTY)