CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

The original subdivision of T4S R34E was by Rufus S. Moore under Contract No. 451, approved February 1, 1884. At this corner he fnd a post, from which a 30" Pine bears N10°E, 190 1ks. The township line between T5S and T6S had been surveyed by J. Cooper under Contract No. 397, approved April 5, 1882.

Index	File	No.	z-2
DIAGRAM			
R341	SC T5S R3 86 S31	35E	

Description of corner evidence found:

No corner monument found.

Rotted and burnt remains of bearing tree bear N10°E, 125.4 ft., with chopped face, but no scribing.

Description of monument and accessories I established to perpetuate the

original location of this corner: Corner set from evidence. Cap is stamped:

Set 2.5" aluminum cap on 2 3/8" aluminum pipe rising 14" above ground. Set steel fence posts 3.0 ft. north and 3.0 ft. east of corner.

T5S R34E R35E

New BT's:

S36 |S31

SC

A 9" P. Pine bears N70.5°W, 38.7 ft., blazed and scribed SC T5S R34E S36 BT.

RLS 1844 1984

A 15" P. Pine bears N70.5°E, 23.2 ft., blazed and scribed: SC T5S R35E S31 BT.

Brass LS 1844 disc in lower end of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found on southwest slope, 26 ft., N60°W from fence corner. Oiad 5160-158 to Road 5160-152 0.9 mi. to Track Road. East to fence Road 5160-152 hits fence 0.3 miles north of corner.

I hereby certify the above described corner monument and/or accessories was established as described on July 10, 1984.

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON JULY 13, 1979 DAVID E. SCOTT 1844

Office of	County of	
for record on the day of	at the within instrument was filed in this	offic UNION COUNTY SURVEYOR
(COUNTY OFFICIAL)	(DEPUTY)	
Form R6-7100-57 (9/71)		Date Received 10-17-84