


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. Z-11

History of original corner establishment:

The original survey of the Standard Parallel along the south boundary of T5S, R35E was by J. Cooper, under Contract No. 397, approved April 5, 1882. At this corner he set a post, from which a 4" Pine bears N89°W, 122 lks.



Description of corner evidence found:

No corner monument found.

Found one bearing tree, a 10" L. Pine, dead and down, bearing N88°W, 80.52 ft. from corner.

Description of monument and accessories established to perpetuate the original location of this corner: Cap is stamped;

Set 2.5" aluminum cap on 2 3/8"x30" aluminum pipe rising 6" above ground. Set 6 ft. steel fence post 3.0 ft. east of corner.

SC  
T5S R35E  
1/4, S33  
RLS 1844  
1984

New BT's:

- A 7" P. Pine bears N12.5°E, 131.7 ft., blazed and scribed: SC 1/4 S33 BT.
- A 6" L. Pine bears N58°E, 31.7 ft., blazed and scribed: SC 1/4 S33 BT.

Brass LS 1844 disc in lower end of blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Compass Declination: 19 3/4°E

Witness: Duane Scott

Corner is found 240 ft. east of road through Vey Ranch, 2.1 mi from Rd 51.

I hereby certify the above described corner monument and/or accessories was established as described on September 6, 1984.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*David E. Scott*

OREGON  
JULY 13, 1979  
DAVID E. SCOTT  
1844

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY  
SURVEYOR**

Date Received 10-17-84  
Date Filed 10-24-84  
By G. LANGLITZ, Deputy  
File No. 995-84 R