CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
A post 3½'x3"x3", 18" in the ground from which:
a 10" pine bears N72°E, 11 lks.
a 12" W. Larch bears N43°W, 89 lks.

Index File No. Z-15

DIAGRAM

SC
T5S R35E

\$\frac{1}{4}\$

RLS 1848

1986

Original corner established in 1881 by Jacob C. Cooper under contract #397

Description of corner evidence found:

A 21½" W. Larch(live) bears N43°W, 89 lks, burned out, faint scribing

Description of monument and accessories I established to perpetuate the original location of this corner: Cap is stamped:

Set 2½"x30" aluminum capped aluminum pipe rising 6" in mound of stones and earth. Set steel fencepost 3' north of corner.

SC T5S R35E \frac{1}{4} S34 RLS 1848 1986

New BT's:

A 6½" W. Larch bears N39°W, 12.9 ft., blazed & scribed: ½ S34 SC BT A 6½" W. Larch bears N41½°E, 42.8 ft. blazed & scribed: SC ½ S34 BT

Painted blazes and attached signs as required in <u>Specifications for Cadastral Surveys</u>, USFS Region 6, March, 1982.

Compass Declination: 19½°E
Witness: J. Sutton
I hereby certify that the above
described corner monument and/or
accessories was perpetuated as
hereon described on July 12, 1986



| | St | EY | |
|---|-----------|-------|------|
| _ | ********* | _ | |
| | | | |
| | | | |
| | | | |

UNION COUNTY

Date Received 8-26-86

Date Filed 9-10-86

51. N. 127. 9/ D

SEE SURVEY 27-86