CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: A post 42'x4"x4", 2 in the ground from which: an 8" pine bears N46°W, 26 lks. an 8" leaning pine bears N66°E, 10 lks.

Index File No. Z-17

DIAGRAM

SC T5S R35E S34|S35 RLS 1848 1986

Original corner established in 1881 by Jacob C. Cooper under contract #397

Description of corner evidence found: None.

Description of monument and accessories I established to perpetuate the original location of this corner: Cap is stamped:

Set 2½"x30" aluminum capped aluminum pipe rising 5" in mound of stones. Set steel fence post 3' north of corner.

- New RP's:
 A 5/8" iron rod with a 1½" aluminum cap bears N00°41'W, 30 ft.
 - A 5/8"x36" iron rod with a 15" aluminum cap bears S89°30'E, 30 ft.

Painted blazes and attached signs as required in Specifications for Cadastral Surveys, USFS Region 6, March, 1982.

Compass Declination: 19岁°E Witness: J. Sutton I hereby certify that the above described corner monument and/or accessories was perpetuated as hereon described on Jul 10, 1986.



SC T5S R35E S34|S35 RLS 1848 1986

REGISTERED PROFESSIONAL LAND SUZVEYOR
Sullar
OREGON JULY 13, 1979 B. A. SUTTON 1 8 4 8

Date Received <u> </u>
Date Filed 9~10~86
BY G. LANGLITZ DEPUTY

UNION COUNTY

SURVEYOR

EE Survey 27-86

Office of	County of
State of,	I hereby certify that the within instrument was filed in this office
for record on the day of.	
	by
(COUNTY OFFICIAL	

Form R6-7100-57 (9/71)