


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not established during original survey.

Index File No. N-2



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner position established by survey and subdivision of Section 19.
At surveyed point set 2½"x30" galvanized pipe with brass cap stamped:

Set pipe 24" in ground. No stones available for mound.

Bearing trees: A Doug. Fir 17" dia. bears N39°E 32.55 ft. scribed
W1/16 S18 BT.

A Doug. Fir 9" dia. bears S60½°E 32.10 ft. scribed
W1/16 S19 BT.

T5S	R36E
	S18
W1/16	— —
	S19
	PLS 1099
	1982

Attached 54-2, 54-4 and 54-9 signs to metal post 6 ft. West of corner. Painted trees and attached signs per Standard Specifications For Cadastral Surveys U.S.F.S. Region 6, October 1979. Attached 54-2 sign to metal post 6' South of corner.

Corner falls on a steep NW slope just below the top of a high hill in mostly Fir and Tamarack thicket.

Compass Declination: 19°E

I hereby certify the above described corner monument and/or accessories was established on August 18, 1982.

Witnesses: G. Wagoner
R. Scott

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Gary L. Langlitz
OREGON
 JULY 22, 1977
GARY L. LANGLITZ
 1099

Office of..... Surveyor..... County of..... Union.....
State of..... Oregon..... I hereby certify that the within instrument was filed in this office

for record on the 4 day of OCTOBER 1982
Howard L. Perry by *Gary L. Langlitz*
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received _____
* GPD-798-276

Date Filed _____

By _____

File No. 636-84R