CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1882, under GLO contract No. 452, H. Gradon set Post 3 ft. long 3 ins. square, 24 ins. in ground for 1/4 Sec. Cormarked 1/4 S on N. face from which:

A Fir 12 in. diam. bears N 40°W, 25 lks. dist. marked 1/4 S. BT.

A Pine 7 ins. diam. bears S70°W, 9 lks. dist. marked 1/4 S. BT.

Index File No. N-3

DIAGRAM		
T5S	R36E	
1 -	18 19	

Description of corner evidence found:

Found a dead standing Fir 18" diam. with opened blaze to visible scribing "S BT" for N.W. BT. Established a point for the corner location. Could find no evidence of original SW BT. (Established point is at record data from found NW BT - S40°E, 16.5 ft.) Could find no evidence of the original corner post.

Description of monument and accessories I established to perpetuate the original location of this corner:

At established point for corner location set 2 1/2" x 30" galvanized pipe with brass cap stamped:
Set pipe 23" in ground with mound of dirt to cap.
Bearing trees: A Douglas Fir 13" dia. bears N15 1/2°E, 42.0 ft. scribed 1/4 S 18 BT.
A Douglas Fir 11" dia. bears S33°E, 17.0 ft. scribed 1/4 S19 BT.
Painted trees and attached signs per Standard Specifications for Cadastral Surveys, U.S.F.S. Region 6, October 1979.
Attached 54-4 sign to metal post 6 ft. west of corner.
Corner falls on north slope 450 ft. East of location tag on gravelled road and 330' west of section board on USFS Rd. S-5049.

Compass Declination: 19°E

I hereby certify the above described corner monument and/or accessories was established on August 11, 1982.

Witnesses: R. Orton

R. Scott

G. Wagoner

REGISTERED PROFESSIONAL LAND SURVEYOR

GARY L. LANGLITZ

Office of Surveyor	County of. Union	1000
State of Oregon I hereby for record on the A. day of Octo Howard L. Perry (COUNTY OFFICIAL)		this office UNION COUNTY SURVEYOR
Orm DC 7100 F7 (0 /71)	9	Date Received

Form R6-7100-57 (9/71)

∵ GPO 799-509