

2

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by General Land Office contract survey


The original notes state:

North between sections 19 and 20

40.00 Set a post 3 ft. long 3 in. square, 24" in ground marked  $\dagger$  south on west face from which a;

Pine 36" dia bears S20°E, 18 lks marked  $\dagger$ SBT;

Pine 5" dia bears S45°W, 25 lks marked  $\dagger$ SBT;



Description of corner evidence found:

In section 19, found 10" Ponderosa Pine in good shape.

In section 20, found stump with scribe.

Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 30" galvanized pipe with an eight inch plate welded to bottom and a bronze cap on top. The hole was back filled with stone and tamped soil.

I stamped the disk.

From the monument the original bearing trees are;


Ponderosa Pine 10" dia bears S45°W, 25 lks.

I established the following new bearing trees;

Ponderosa Pine 18" dia N73°E at a distance of 20 ft. and scribed  $\dagger$ SBT

The distance measured to center of respective trees on level.

I placed bearing tree signs on both old and new bearing trees and painted stripe around trees. I placed a steel fence post with USFS sign 5444 attached near the corner.



Office of \_\_\_\_\_ County Surveyor \_\_\_\_\_ County of Union \_\_\_\_\_  
State of Oregon \_\_\_\_\_, I hereby certify that the within instrument was filed in this office  
for record on the 18 day of August, 1970, at 12 o'clock P.m., (signed)  
\_\_\_\_\_ County Surveyor \_\_\_\_\_ by \_\_\_\_\_ (DEPUTY)  
(COUNTY OFFICIAL)

<b>UNION COUNTY SURVEYOR</b>
Date Received _____
Date Filed _____
By _____
File No. 642-84R