


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. T-3

History of original corner establishment:

Not established during original survey




Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

Corner position established by survey and subdivision of Section 30. At surveyed point set 2 1/2"x30" galvanized pipe with brass cap stamped:



Set pipe 24" in ground with mound of stone to cap. Bearing trees:

A Lodgepole Pine 10" diam. bears N 6 1/2°E 30.3 ft. scribed C 1/4 S30 BT.

A Ponderosa Pine 7" diam. bears N 80 1/2°E 67.9 ft. scribed C 1/4 S30 BT.

Attached 54-4 and 54-9 signs to metal post 6' north of corner. Attached signs and painted trees per Standard Specifications for Cadastral Surveys, USFS Region 6, October, 1979.

Corner falls in bottom of draw. Course S.E. 50 ft. South of old logging road closed off.

Compass Declination: 19°E

I hereby certify the above described corner monument and/or accessories was established on August 25, 1982.

Witnesses: R. Orton
G. Wagoner
R. Scott

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Gary L. Langlitz
OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Office of..... Surveyor..... County of..... Union.....
State of..... Oregon..... I hereby certify that the within instrument was filed in this office
for record on the 4 day of OCTOBER 1982
Howard L. Perry by *Gary L. Langlitz*
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received _____
GPO 799-509

Date Filed _____

By _____

File No. 652-84R