CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment: Corner established in 1882 by H. Gradon, under General Land Office Contract No. 452.

Surveyor General's Records state:

Set a post 4 ft. long, 4 ins. square, 24 ins. in the ground for 1/4 Sec. Cor., marked 1/4S on W. Face. From which:

A Pine 20 ins. diam. bears N65^oE, 60 lks. dist. marked 1/4S BT.

A Pine 45 ins. diam. bears N45^OW, 6 lks. dist. marked 1/4SBT



Description of corner evidence found:

A diligent search was made and no evidence of the corner or its accessories could be found.

6

Description of monument and accessories I established to perpetuate the original location of this corner: At surveyed point established by single proportion measurements set 2½"x30" galvanized pipe with brass cap stamped:

Set pipe 24" in ground with mound of stone to cap.

From which:

A Douglas Fir 11th in dia. bears N14^oE, 31.1 ft., scribed 1/4S29 BT.

A Douglas Fir 10th in dia. bears S5^oW, 38.0 ft., scribed 1/4S30BT.

Attached 54-3 signs to both BT's. Attached brass washer stamped LS 1294 to

foot blaze of both BT's. Painted blazes and 6" band around both BT's orange. Attached 54-4 sign to metal fence post 5' North of corner.

T5S R36E WM **S29** פל 19 OR PLS 1294

I hereby certify the above corner monument was reestablished as herein described on October 31, 1979.

WITNESSES: R. Orton

D. Allen

REGISTERED **PROFESSIONAL** AND SURVEYOR WAS OREGON
SEPTEMBER 23, 1977
HOWARD L. PERRY
1 2 9 4

Office of County Surveyor Count State of Oregon , I hereby certify that the		
for record on the day of		UNION COUNTY
(COUNTY OFFICIAL)	(DEPUTY)	
m DC 7100 E7 (0/71)		Date Received

Form R6-7100-57 (9/71)

☆ GPO 799-509 Date Filed File No. 653-84R