


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. U-3

History of original corner establishment:
Not established during original survey.



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner position established by survey and subdivision of Section 30.
At surveyed position set 2½"x30" galvanized pipe with brass cap stamped:
Set pipe 24" in ground with mound of stone and dirt to cap.

Bearing trees: A Ponderosa Pine 14" dia. bears N22°E, 30.6 Ft.
scribed CS1/16 S30 BT.
A Ponderosa Pine 11" dia. bears N82°W, 61.4 Ft.
scribed CS1/16 S30 BT.

T5S R36E
C
S1/16 | S30
C
PLS 1099
1982

Attached signs and painted trees per Standard Specifications For Cadastral Surveys, U.S.F.S., Region 6, October 1979.

Attached 54-2, 54-4 & 54-9 signs to metal post 6 Ft. West of corner.

Corner falls on SW slope 41.6 Ft. North of E-W fence and 150 Ft. East of bottom of draw course SW.

Compass Declination: 19° East

I hereby certify the above described corner monument and/or accessories was established on August 24, 1982.

Witnesses: R. Orton
G. Wagoner
R. Scott

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Gary L. Langlitz
OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Office of.....Surveyor..... County of..... Union
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the...4... day of...OCTOBER... 1982
.....Howard L. Perry..... by *Gary L. Langlitz*
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY
SURVEYOR
Date Received _____
Date Filed _____
By _____
File No. 655-84R