

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. V-7


History of original corner establishment:

Corner established in 1882 by H. Gradon, under General Land Office Contract No. 452.

Surveyor General's Records state:

Set post 3 ft. long, 3 inches square, 24 inches in the ground for 1/4 sec. cor. marked 1/4 S on N. face from which:

- A Pine 8 inch. diameter bears N55⁰E, 27 lks, dist., marked 1/4 S BT.
- A Pine 10 inch. diam. bears S15⁰W, 11 lks dist., marked 1/4 S BT.



Description of corner evidence found:

A diligent search was made and no evidence of the corner or its accessories could be found.

Description of monument and accessories established to perpetuate the original location of this corner: At surveyed point established by single proportion measurements, set 2 1/2" x 30" galvanized pipe with brass cap stamped:

Set pipe 20" in ground with mound of stone to cap.

From which:

A Douglas Fir 11" in dia. bears N63⁰W, 58.1 ft., scribed 1/4 S29 BT.

A Douglas Fir 11" in dia. bears S18⁰W, 30.7 ft., scribed 1/4 S32 BT.

Attached 54-3 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs orange. Attached 54-4 sign to metal fence post 5' West of corner.

T5S R36E WM

S29

1/4 ———|—————

S32

1979

OR PLS 1294

I hereby certify the above corner monument was reestablished as herein described on November 1, 1979.

Witnesses: R. Orton
D. Allen

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

OREGON
SEPTEMBER 23, 1977
HOWARD L. PERRY
1294

Office of.....County Surveyor..... County of.....Union.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 1979

..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 89 GPO-798-276

Date Filed _____

By _____

File No. 661-84R