


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX FILE NO. X-6

History of original corner establishment:

None set



Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner: At surveyed point set 2½"x30" galvanized pipe with brass cap stamped:  
Set pipe 24" in ground with stones not available for mound.  
From which:  
A Douglas Fir 11" in dia. bears S89°E, 37.5 ft., scribed CW 1/16 S32BT.  
A Douglas Fir 8" in dia. bears S34°W, 28.0 ft., scribed CW 1/16 S32BT.  
Attached 54-3 signs to both BT's. Attached brass washer stamped LS 1294 to foot blaze of both BT's. Painted blazes and 6" band around both BT's orange. Attached 54-2 and 54-4 signs to metal fence post 5' East of corner. Attached 54-2 and 54-9 signs to metal fence post 5' North of corner.

T5S R36E WM  
W 1/16  
C ———+———— C  
S32  
1979  
OR PLS 1294

I hereby certify the above corner monument was established as herein described.  
October 26, 1979  
WITNESSES: R. Orton  
D. Allen

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

OREGON  
SEPTEMBER 23, 1979  
**HOWARD L. PERRY**  
1294

Office of.....County..Surveyor..... County of...Union.....  
State of.....Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19..79  
..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

<b>UNION COUNTY SURVEYOR</b>
Date Received _____ <small>☆ GPO—798-276</small>
Date Filed _____
By _____
File No. <u>666-84R</u>