


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:


None set

INDEX FILE NO. X-7



Description of corner evidence found:

Description of monument and accessories established to perpetuate the original location of this corner: At surveyed point set 2 1/2 x30" galvanized pipe with brass cap stamped: Set pipe 23" in ground with no stones available for mound.



From which:

A Douglas Fir 7" in dia. bears N70°E, 7.9 ft., scribed C 1/4 S32 BT.

A Douglas Fir 14" in dia. bears S62°W, 12.2 ft., scribed C 1/4 S32 BT.

Attached 54-3 signs to both BTs. Attached brass washer stamped LS1294 to foot blaze of both BTs. Painted blazes and 6" band around BT's orange.

Attached 54-2, 54-4 and 54-9 signs to metal fence post 5' west of corner.

I hereby certify the above corner monument was established as herein described.

October 26, 1979

Witnesses: R. Orton
D. Allen

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
SEPTEMBER 23, 1977
HOWARD L. PERRY
1294

Office of..... County Surveyor..... County of..... Union
State of..... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19..79

(COUNTY OFFICIAL)

by

(DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____
GPO 799 509

Date Filed _____

By _____

File No. 667-84 R