


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX FILE NO. Y-8


History of original corner establishment:

None set



Description of corner evidence found:

Description of monument and accessories established to perpetuate the original location of this corner: At surveyed point set 2½"x30" galvanized pipe with brass cap stamped:
Set pipe 24" in ground. No stones available for mound.



From Which:

A Douglas Fir 6" in dia. bears S51°W, 7.3 ft., scribed SE 1/16 S32BT.
A White Fir 10" in dia. bears S81°E, 43.0 ft., scribed SE 1/16 S32BT.
Attached 54-3 signs to both BT's. Attached brass washer stamped LS 1294 to foot blaze of both BT's. Painted blazes and 6" band around both BT's orange. Attached 54-2 and 54-4 signs to metal fence post 5' East of corner. Attached 54-2 and 54-9 signs to metal fence posts 5' North of corner.

I hereby certify the above corner monument was established as herein described.

October 25, 1979

WITNESSES: R. Orton
D. Allen

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
SEPTEMBER 23, 1977
HOWARD L. PERRY
1 2 9 4

Office of.....County Surveyor..... County of.....Union.....
State of.....Oregon..... I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19...79

..... by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR

Date Received _____
GPO 799 509

Date Filed _____

By _____

File No. 670-84R