CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original corner established in 1881 by Jacob C. Cooper under contract #397.

A Pine post was set, from which: A 24" Pine bears N45°E, 14 lks. A 24" Pine bears N72°W, 43 lks.

Index File No. Z-	25
DIAGRAM	
T5S R35E R36E <u>S36 S31</u> RLS 1848 1986	

Description of corner evidence found:

A 35" Pine stump 2½' high bears N72°W, 43 lks., open blaze, BT visible.

Description of monument and accessories l'established to perpetuate the original location of this corner:

Cap is stamped:

Set $2\frac{1}{2}$ "x30" aluminum capped aluminum pipe rising 4" in mound of stones. Set steel fence post 3' north of corner.

T5S R35E R36E <u>S36|S31</u> RLS 1848 1986

New BT's:

A 12" W. Larch bears N48°W, 9.8 ft., blazed & scribed: T5S R35E S36SCBT A 9" W. Larch bears N24°E, 6.2 ft. blazed & scribed: T5S R36E S31SCBT

Painted blazes and attached signs as required in <u>Specifications for Cadastral Surveys</u> USFS region 6, March, 1982. Attatched ¾" brass washers marked RLS 1848 to blazes.

Compass Declination: 19½°E
Witness: J. Sutton

I hereby certify that the above described corner monument and/or accessories was perpetuated as hereon described on May 26, 1986.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 13, 1979
B. A. SUTTON
1 8 4 8

UNION COUNTY SURVEYOR

Date Received 9-17-86

Date Filed 9-19-36

BY G. LANGLITZ DONT

File No. 142-86 R

Office of	County of	See	DURVEY	27-86
	ereby certify that the within instrument was file			
for record on the day of				
	by			
(COUNTY OFFICIAL)	(DEPUTY)			