CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1882 by H. Gradon, under General Land Office Contract No. 452.

Surveyor General's records state:

Set post $3\frac{1}{2}$ ft. long, 3 ins. square, 18 ins. in ground in a clearing on River bottom for standard 1/4 sec. cor. marked 1/4 S. SC on N. face from which:

A Pine 6" diam. bears N70^oE, 38 lks. dist. marked S.C. 1/4 S. B.T.

A Pine 4" diam. bears N21⁰W, 33 lks. dist. marked S.C. 1/4 S. B.T.

Index File No. Z-7		
DIAGRAM		
SC T5S R36E S32		
1/4 ———		

Description of corner evidence found:

A diligent search was made and no evidence of the corner or its accessories could be found.

Description of monument and accessories I established to perpetuate the original location of this corner: At surveyed point established by single proportion measurements set 2½" x 30" galvanized pipe with brass cap stamped: Set pipe 19" in ground to rock with mound of stone to cap.

From which:

F

A Western Larch 9" in diam. bears N19⁰W, 102.4 ft.,

scribed 1/4 S32 SC BT. A Spruce 8" in dia. bears N40°E, 26.3 ft., scribed 1/4 S32 SC BT.

Attached 54-3 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs. Attached 54-2 and 54-4 signs to metal fence post 7' West of corner.

SC R36E T5S WM **S32** 1/4 1979 OR PLS 1294

I hereby certify the above corner monument was reestablished as herein described on November 1, 1979.

Witnesses: R. Orton

D. Allen

REGISTERED **PROFESSIONAL** AND SURVEYOR OREGON
SEPTEMBER 23, 1977
HOWARD L. PERRY

Office of County Surveyor	County of Union	1294
State ofOregon , I hereby certify tha	t the within instrument was filed in	this office
for record on the day of, 19.79.		UNION COUNTY
(COUNTY OFFICIAL)	(DEPUTY)	SURVEYOR
rm R6-7100-57 (9/71)		Date Received
		Date Filed