


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. Z-13

History of original corner establishment: Corner established in 1881 by Jacob C. Cooper under Contract No. 397.

A post was set, from which a 20" Pine bears N45°W, 10 lks. and a 25" Pine bears N45°E, 29 lks.



UNION COUNTY SURVEYOR
Date Received <u>6-19-86</u>
Date Filed <u>6-19-86</u>
By <u>G. Langlitz, Deputy</u>
File No. <u>89-86 R</u>

Description of corner evidence found:

Found decayed remains of base of post in rock mound.

Bearing trees found:

- 28" P. Pine (live, good condition) bears N25°E (Original notes say N45°E) 29 lks., open blaze, scribing visible: 5S R36E S.
- 20" P. Pine (dead & down) bears N45°W, 10 lks, open blaze, scribing visible: T5S R36E S33 BT.
- 6.5" L. Pine (dead, standing) bears S20°W, 10.2 ft., open blaze, scribing visible: T6S R36E S4 BT (not in original notes).

Description of monument and accessories established to perpetuate the original location of this corner:

Cap is stamped: SC
T5S R36E
S33 | S34
RLS 1848
1986

Set 2.5"x30" aluminum capped aluminum pipe rising 8" in mound of stones. Set steel fence post 3 ft. north of corner.

New BT's:

- 6.5" L. Pine bears N15 1/2°W, 34.6 ft., blazed & scribed: T5S R36E S33 SCBT


Attached 3/4" brass washer marked LS 1848 to blazes. Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

To find corner: At the intersection of 5125198, 5125205 & 5125199 there is an old rock quarry. The corner is 200 ft. northwest on a northwesterly slope.

Compass Declination: 19 1/2°E

Witness: J. Sutton

I hereby certify that the above described corner monument and/or accessories was perpetuated as hereon described on May 30, 1986.



Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)