


Index File No. 715 A-15  
T 4 S R. 37 E  
Merid. West

CORNER RECORD (SEARCH)

Tract or Survey No. \_\_\_\_\_  
Cor. No. \_\_\_\_\_

R.D. La Grande County Union  
N.F. William-Whitman State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

12" <sup>L.P.</sup> ~~tree~~ down + very poor condition  
Scribbling visible

PHOTO IDENTIFICATION DATA

Photo No. ENW 11-189  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By du pos.  
*Signature*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Co. is on south end of small  
glade or opening.

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
*Agency*

Signature J. Williams Title C.E.T. Division \_\_\_\_\_ Headquarters \_\_\_\_\_ Date 6-9-68  
7100-52  
REV. 65 5

**UNION COUNTY SURVEYOR**

Date Received \_\_\_\_\_

Date Filed 12-23-87

By G. LANGLITZ, DEPUTY

File No. 339-87R

A-15

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


**History of original corner establishment:**

J. C. Cooper conducted the survey of the First Standard Parallel, Township 5 South, Ranges 34, 35, 36, and 37 East, W.M., together with additional Township and Range lines, under GLO contract No. 397 dated July 14, 1881.

Cooper set a post for the corner point, from which:

A pine 9" dia. bears S 2 E at 13 lks. dist.

A-15



**Description of corner evidence found:**

BT-

A stump hole bears S 2 E at 13 lks. dist., with blaze remains lying alongside, blaze mkd. 1/4 S BT.

**Description of monument and accessories established to perpetuate the original location of this corner:**

Corner point re-established from the one original found bearing tree. At the corner point, set 2 1/2" x 30" aluminum pipe 24" into the ground, with 36" dia. stone mound around it. 2 1/2" dia. aluminum cap mkd. as shown in the corner diagram.

From the corner point: (New BT's)

A 7" dia. Ponderosa Pine bears N 78 E at 34.9 ft. dist. mkd. 1/4 S 34 BT.  
A 16" dia. Douglas Fir bears S 80 W at 23.9 ft. dist. mkd. 1/4 S 3 BT.

Attached U.S.F.S. 54-9 and 54-3 signs to the bearing trees, and painted the blaze and a 6" band around the bearing trees red. Attached a 3/4" dia. brass I.D. washer, mkd. PLS 1206, between the B and T scribes. Set a steel fence post 4' South of the monument with U.S.F.S. 54-9 sign attached to it. Used 18 1/2° declination on a staff compass for readings to the bearing trees, and used a steel tape to measure to a nail set in the side of the bearing trees at the base.

This corner was monumented to U.S.F.S. specifications on Sept. 1987, witnessed by Larry McBroom and Tim Rouse.

<b>UNION COUNTY SURVEYOR</b>
Date Received <u>5-1-89</u>
Date Filed <u>5-15-89</u>
By <u>G. LANGLITZ DEPUTY</u>
File No. <u>50-89 R</u>

Office of...County Surveyor..... County of...Union.....  
State of...Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*James D. Hanley*  
**OREGON**  
SEPTEMBER 23, 1977  
JAMES D. HANLEY  
1206