CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None, corner established this survey.

C-3 DIAGRAM R37E T5S C 1/4.5 6 PLS 1206 1987

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner point: set a $2\frac{1}{2}$ " x 30" aluminum pipe 24" into the ground, with no stone mound, as none were available within limits.

 $2\frac{1}{2}$ aluminum cap marked as shown in the corner diagram.

From the corner point: (Bearing Trees)
A 10" dia. Western Larch bears S 65° E at 28.2 ft. dist., mkd. C 1/4 S 6 BT.
A 7" dia. Lodgepole Pine bears N 20° W at 48.2 ft. dist., mkd. C 1/4 S 6 BT.

Attached U.S.F.S. 54-9 and 54-3 signs to the bearing trees, and painted the face of the blaze and a 6" band around the bearing trees red. Attached a 3/4" dia. I.D. washer, mkd. PLS 1206, between the B and T scribes. Set a steel fence post 4' dist. with U.S.F.S. 54-9 and 54-2 signs attached. Used $18\frac{1}{2}$ declination on a staff compass for readings to the bearing trees, and used a steel tape to measure to a nail set in the side of the trees at the base.

This corner was monumented to U.S.F.S. specifications on June 11, 1987, witnessed by Tom Fisk and Larry McBroom.

UNION COUNTY SURVEYOR Date Received_5-1-89 Date Filed 5-15-89 ANGLITZ DOUT Office of County Surveyor County of Union State of Oregon , I hereby certify that the within instrument was filed in this office for record on the...... day of...... , 19..... by COUNTY OFF (DEPUTY)

Form R6-7100-57 (9/71)

REGISTERED **PROFESSIONAL** LAND SURVEYOR

> OREGON SEPTEMBER 23, 1977 JAMES D. HANLEY 1206

mest

☆ GPO---798-276