CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None, corner established this survey.

C-7

DIAGRAM
T5S R37E

C1/4 S 5

PLS 1206

1987

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner point: set a $2\frac{1}{2}$ " x 30" aluminum pipe 26" into the ground, with a 36" dia. stone mound around it. $2\frac{1}{2}$ " aluminum cap marked as shown in the corner diagram.

From the corner point: (Bearing Trees)

A 9" dia. Ponderosa Pine bears N 69° E at 40.9 ft. dist., mkd. C 1/4 S 5 BT.

A 13" dia. Ponderosa Pine bears N 78° W at 17.2 ft. dist., mkd. C 1/4 S 5 BT.

Attached U.S.F.S. 54-9 and 54-3 signs to the bearing trees, and painted the face of the blaze and a 6" band around the bearing trees red. Attached a 3/4" dia. I.D. washer, mkd. PLS 1206, between the B and T scribes. Set a steel fence post 4' North with U.S.F.S. 54-9 sign attached. Used $18\frac{1}{2}$ 0 declination on a staff compass for readings to the bearing trees, and used a steel tape to measure to a nail set in the side of the trees at the base.

This corner was monumented to U.S.F.S. specifications on June 25, 1987, witnessed by Tom Fisk, Larry McBroom and Tim Rouse.

•	witnessed	ру	Tom	Fisk,	Larry	McBroom	and	Tim	Rouse	on oune	;
										VAIUS VAUS	COUNTY
										Date Received_	5-1-89
										Date Filed 5	-15-87
_			7							By G, LANG	GLITZ DOPUM
Oi	fice ofCour	17;	ourv	ey.or	Cou	nty ofUni.	מב	• • • • • • • • • • • • • • • • • • • •		55	DOP
51	ete of Oregor	·····		hereby cer	tify that th	e within instru	ment wa	s filed	in this of	File No. 55	-09/
fo	r record on the	day	of	••••••	• • • • • • • • • • • • • • • • • • • •	, 19					
•••	(COUN	ITY OFFI	CIAU	SISTEDE	by	••••••	(DEPUTY		•••••	•••	

Form R6-7100-57 (9/71)

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON SEPTEMBER 23 1977 JAMES D. HANLEY 1206

☆ GPO--798-276