CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None, corner established this survey.

D-4 DIAGRAM T5S R37E SE1/16·S 6 PLS 1206 1987

9 Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner point: set a $2\frac{1}{2}$ " x 30" aluminum pipe 22" into the ground, with a 36" dia. stone mound around it. $2\frac{1}{2}$ " aluminum cap marked as shown in the corner diagram.

From the corner point: (Bearing Trees)
A 8" dia. Lodgepole Pine bears S 56° E at 11.6 ft. dist., mkd. SE 1/16 S 6 BT.
A 8" dia. Lodgepole Pine bears N 39° W at 6.3 ft. dist., mkd. SE 1/16 S 6 BT.

Attached U.S.F.S. 54-9 and 54-3 signs to the bearing trees, and painted the face of the blaze and a 6" band around the bearing trees red. Attached a 3/4" dia. I.D. washer, mkd. PLS 1206, between the B and T scribes. Set a steel fence post 4' dist. with U.S.F.S. 54-9 and 54-2 signs attached. Used $18\frac{1}{2}$ °0 declination on a staff compass for readings to the bearing trees, and used a steel tape to measure to a nail set in the side of the trees at the base.

Form R6-7100-57 (9/71)

PROFESCIONAL LAND SURVEYOR

OREGON, SEPTEMBER 23, 1977 JAMES D. HANLEY 1206

Hanle

Mmissel

(DEPUTY)

☆ GPO---798-276