

T. 5 S., R. 37 E., Willamette Meridian, Oregon

CHAINS

The following field notes describe the remonumentation of certain original corner points, township 5 south, range 37 east, Willamette Meridian, Oregon, as provided for in the Special Instructions, Group Number 1000, Oregon, dated July 13, 1979, "Investigation of Physical Evidence of Corner Positions and Accessories, Followed by Remonumentation of Corner Points, with New Accessories when Needed."

The remonumentation of original corner points was made at the request of the United States Forest Service, in conjunction with their Land Line Location Program.

The mean magnetic declination is 20° E.

Subdivisions, T. 5 S., R. 37 E., Willamette Meridian, Oregon

(Remonumenting corners established by William R. Graden, U. S. Deputy Surveyor, in 1882)

The ¼ sec. cor. of secs. 7 and 11, determined at recent bearing and distance from the remains of the original bearing trees:

A lodgepole pine snag, 10 ins. diam., bears N. 15° E., 89 lbs. dist., with scribe marks ¼ S BT visible on open blaze.

A burned fir stump, 25 ins. diam., bears S. 20° W., 19 lbs. dist., no marks visible.

At the corner point

Set an aluminum post, 25 ins. long, 2 1/2 ins. diam., at

CHAINS

T 5 S R 37 E
¼ S 11
1982

from which new bearing trees

A lodgepole pine, 10 ins. diam., bears S. 30° W., 42 1/2 lbs. dist., mkd. ¼ S11 BT.

A fir, 8 ins. diam., bears N. 66° W., 39 lbs. dist., mkd. ¼ S2 BT.

Set a steel fence post alongside aluminum post.

**UNION COUNTY
SURVEYOR**

Received 9-26-83

Filed 11-18-83

By G. LANGLITZ, DEPUTY

File No. 420-83 R

NOTE: MICROFICHE CARD IS AVAILABLE IN COUNTY SURVEYOR'S RECORDS.