

## T. 5 S., R. 37 E., Willamette Meridian, Oregon

CHARGE

The following field notes describe the remonumentation of certain original corner points, township 5 south, range 37 east, Willamette Meridian, Oregon, as provided for in the Special Instructions, Group Number 1000, Oregon, dated July 13, 1979, "Investigation of Physical Evidence of Corner Positions and Accessories, Followed by Remonumentation of Corner Points, with New Accessories when Needed."

The remonumentation of original corner points was made at the request of the United States Forest Service, in conjunction with their Land Line Location Program.

The mean magnetic declination is 20° E.

Subdivisions, T. 5 S., R. 37 E.,  
Willamette Meridian, Oregon

(Remonumenting corners established by William R. Graden,  
U. S. Deputy Surveyor, in 1882)

The  $\frac{1}{4}$  sec. cor. of secs. 13 and 14, remonumented with the original basalts stones, 12 x 10 x 3 ins., loosely set 6 ins. in the ground, no marks visible, from which the remains of the original bearing trees:

A root hole, bears N. 30° E., 23 lbs. dist., with a down and decayed fir alongside, 6 ins. diam., no marks visible.

A fir, 27 ins. diam., bears N. 10° W., 23 lbs. dist., with healed bane.

At the corner point

Set an aluminum post, 28 ins. long,  $\frac{3}{4}$  ins. diam., 13 ins. in the ground, to solid rock, in a mound of stone,  $\frac{3}{4}$  ft. base, to top, with aluminum cap and.

T 5 S R 37 E  
S 14 | S 13  
1982

from which a new bearing tree

A fir, 28 ins. diam., bears S. 66° E., 45 lbs. dist., mhd.  $\frac{1}{4}$  #13 BT.

Deposit corner stone and set a steel fence post alongside aluminum post.

UNION COUNTY  
SURVEYOR

Date Received 9-26-83

Date Filed 11-18-83

By G. LANGLITZ, DEPUTY

File No. 413-83 R

NOTE: MICROFICHE CARD AVAILABLE IN COUNTY SURVEYOR'S RECORDS.