CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

William R. Gradon conducted the survey of Town-ship 5 South, Range 37 East, W.M., under contract No. 445 dated June 1, 1882.

Gradon set a basalt stone 24" x 10" x 5", 18" into the ground, marked with 3 notches on the South and East edges, from which:

A black pine 10" dia. bears N 5 E at 212 lks. dist. A black pine 12" dia. bears S 35 E at 40 lks.dist. A black pine 10" dia. bears S 50 W at 38 lks. dist. A black pine 13" dia. bears N 65 W at 50 lks. dist.

N-13DIAGRAM T5S R37E S16 S15 S21 | S22 PLS 1206 1987

Description of corner evidence found:

Found a Basalt stone 18" x 13" x 4", marked with 3 grooves on the South side and 3 grooves on the East side.

BT's-

A rotted tree, size indeterminable, bears N. 5° E. at 140 ft. dist., mkd. T5S R37E S 15 / BT.

A root hole bears S. 35° E. at 26.4 ft. dist.

A rotted tree, size indeterminable, bears S. 50° W. at 25.1 ft. dist., mkd. S 21 / BT.

A rotted tree, size indeterminable, bears N. 65° W. at 33.0 ft. dist., mkd. / BT.

Description of monument and accessories I established to perpetuate the original location of this corner:

In place of the original corner stone, set a $2\frac{1}{2}$ " x 30" aluminum pipe with a $2\frac{1}{2}$ " aluminum cap, 22" into the ground, with a 36" stone mound. Cap is marked as shown in the corner diagram. The original stone was buried 1' North of the monument.

From the corner point: (New BT's)
A 7" dia. Lodgepole Pine bears N. 59° W. at 12.0 ft. dist.,

mkd. T5S R37E S 16 BT. A 8" dia. Lodgepole Pine bears S. 31° E. at 21.3 ft. dist.,

mkd. T5S R37E S 22 BT.

A 14" dia. Tamarack bears S. 52° W. at 31.6 ft. dist., mkd. T5S R37E S 21 BT.

A 8" dia. Tamarack bears N. 61° E. at 97.1 ft. dist., mkd. T5S R37E S 15 BT.

Set a steel fence post 4° East from the monument and attached a USFS 54-9 sign. Painted the face of the blaze and a 6" band around the bearing trees red. Attached I.D. washer and USFS 54-9 and 54-3 signs to the bearing trees. Used $18\frac{1}{2}$ ° declination on a staff compass for readings to the bearing trees. Used a steel tape to measure to a nail set in the side of the trees. The 3/4" dia. brass I.D. washer mkd. PLS 1206 was nailed between the B and T scribes.

This corner was monumented to USFS specifications on August 12

This corner was monumented to USFS specifications on August 12, 1987, witnessed by Larry McBroom and Tim Rouse.

UNION COUNTY SURVEYOR Office of County Surveyor County of Union Data Received 5-1-89 State of Oregon ... , I hereby certify that the within instrument was filed in this office "Date Filed 5-15-89 for record on the...... day of....... , 19..... By G. LANGLITZ, DOPUTY by COUNTY OFFICIALL (DEPUTY) File No. 71-89 R REGISTERED **PROFESSIONAL**

Form R6-7100-57 (9/71)

LAND SURVEYOR

ameral Hanle

OREGON SEPTEMBER 21 1977 JAMES D. HANLEY 1206

☆ GPO---798-276