


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

S-14

History of original corner establishment:

None, corner established this survey.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

At the corner point: set 2½" x 30" aluminum pipe 26" into the ground with 36" dia. stone mound around it. 2½" aluminum cap mkd. as shown in the corner diagram.

From the corner point: (Bearing trees)  
A 16" dia. Western Larch bears N 77 E at 18.1 ft. dist. mkd. NW1/16 S 27 BT  
A 8" dia. Spruce bears S 31 W at 16.4 ft. mkd. NW1/16 S 27 BT

Attached U.S.F.S. 54-9 and 54-3 signs to the bearing trees, and painted the face of the blaze, and a 6" band around the bearing trees red. Attached a 3/4" dia. I.D. washer, mkd. PLS 1206, between the B and T scribes. Set a steel fence post 4' South with U.S.F.S. 54-9 and 54-2 signs attached. Used 18½° declination on a staff compass for readings to the bearing trees, and used a steel tape to measure to a nail set in the side of the trees at the base.

This corner was monumented to U.S.F.S. specifications on October 26, 1987, witnessed by Tom Fisk, Larry McBroom and Andy Warlette.

<b>UNION COUNTY SURVEYOR</b>
Date Received <u>5-1-89</u>
Date Filed <u>5-15-89</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>81-89 R</u>

Office of... County Surveyor..... County of... Union  
State of... Oregon..... I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....  
..... by .....

(COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

REGISTERED PROFESSIONAL LAND SURVEYOR

*James D. Hanley*  
OREGON  
SEPTEMBER 23, 1977  
JAMES D. HANLEY  
1206