

T-21

T. 5 S., R. 37 E., Willamette Meridian, Oregon

CHARGE

The following field notes describe the remeasurement of certain original corner points, township 5 south, range 37 east, Willamette Meridian, Oregon, as provided for in the Special Instructions, Group Number 1000, Oregon, dated July 13, 1979, "Investigation of Physical Evidence of Corner Positions and Accessories, Followed by Remeasurement of Corner Points, with New Accessories when Needed."

The remeasurement of original corner points was made at the request of the United States Forest Service, in conjunction with their Land Line Location Program.

The mean magnetic declination is 20° E.

Subdivisions, T. 5 S., R. 37 E.,  
Willamette Meridian, Oregon

(Remeasuring corners established by William E. Graden,  
U. S. Deputy Surveyor, in 1882)

The  $\frac{1}{4}$  sec. cor. of secs. 25 and 26, determined at record bearing and distance from the remains of an original bearing tree:

A sawed larch stump, 12 ins. diam., bears S. 75° W., 16 lks. dist., with scribe mark T visible on decayed opened blaze.

At the corner point

Set an aluminum post, 28 ins. long,  $2\frac{1}{2}$  ins. diam., 24 ins. in the ground, in a collar of stone, with aluminum cap and.

T 5 S R 37 E  
k  
S 26 | S 25  
1982

from which new bearing trees

A larch pole pine, 10 ins. diam., bears S. 60° E., 82 lks. dist., shd. k 823 NT.

A hemlock, 9 ins. diam., bears S. 34° W., 26 lks. dist., shd. k 824 NT.

Set a steel fence post alongside aluminum post.

Corner is located 70 lks. W. of dirt road, 20 lks. wide, bears N. 40° W. and S. 40° E.

**UNION COUNTY  
SURVEYOR**

Date Received 9-26-83

Date Filed 11-18-83

By G. LANGLITZ

File No. 410-83R

NOTE: MICROFICHE CARD

AVAILABLE IN COUNTY SURVEYOR'S  
RECORDS.